

H3C switch port aggregation not working



Overview

Troubleshooting Ethernet link aggregation This section provides troubleshooting information for common issues with Ethernet link aggregation. In an aggregate link, traffic is distributed across the member. Port aggregation between H3C and 3Com Switches?

Is it possible to aggregate ports between a H3C S5500-EI SFP switch and a 3Com 5500G-EI SFP switch?

I. The 3Com 5500G_SFP_EI connect ok but the H3C complains and then loses. The H3C is configured with LACP dynamic. To check LACP settings on the H3C Switch side the used command “display link-aggregation verbose” Loadsharing Type: Shar -- Loadsharing, NonS -- Non-Loadsharing Port Status: S -- Selected, U -- Unselected, I -- Individual Flags: A -- LACP_Activity, B -- LACP_Timeout, C -- Aggregation, D --. Lets start how to configure link aggregation on h3c/hpn switches.

Article Content

H3C Three-Layer Aggregation

H3C Three-Layer Aggregation 1. Configuration steps The switch needs to enter the interface and change the interface to Layer 3 mode. (Routers do not need to change, the default

H3C S5830 Switch Series Configuration Examples

The authentication port (UDP) used by RADIUS servers is 1812 according to standard RADIUS protocols. However, the port (UDP) is set to 1645 on an H3C device that functions as the

H3C S6890 Switch Series Ethernet Link Aggregation Configuration

When you are working on a live network, make sure you understand the potential impact of every command on your network. This document assumes that you have basic knowledge of Ethernet link

Horror Network: Creating link-aggregation on h3c/hpn switch.

Link aggregation is a computer networking term to describe various methods of combining (aggregating) multiple network connections in parallel to increase throughput beyond what a single

Port aggregation between H3C and 3Com Switches? | Comware

Is it possible to aggregate ports between a H3C S5500-EI SFP switch and a 3Com 5500G-EI SFP switch? I have tried linking two aggregate static ports on each switch but with no success.

H3C S5120V3-EI SERIES TROUBLESHOOTING MANUAL Pdf

Replace the local port with a new one to verify that the local port is operating correctly. Replace the peer port with a new one to verify that the peer port is operating correctly.

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: <https://www.activa.net.pl>

Email: sales@activa.net.pl

Phone: +48 662 748 193

Address: ul. Cybernetyki 7B, 02-677 Warsaw, Poland

This document is for informational purposes only. Specifications subject to change without notice.

